

ATTACHMENT 4: PHOTO SHEET



Photo ¹~~5~~: Spring 1 area located near southern property boundary. No single source is apparent as water is laterally spread. The spring is not connected to any stream upgradient from the area. (6/9/09)



Photo ²~~6~~: Proposed location of Point of Diversion #¹ reservoir and dam. View looking downstream on Spring 1 drainage. Surrounding meadow is place of use for flood irrigation. (6/9/09)



Photo **3**: View upstream from POD #**1** on Spring 1 drainage. (6/9/09)



Photo **4**: Spring 1 drainage ends just passed northern property boundary. (9/22/09)



Photo 9: Looking south at End of Spring 1 drainage just north of the northern property boundary. The drainage divides into distributary channels and disappears into an alluvial fan type structure (9/22/09)



Photo 10: Place of use for irrigation on Tweed's property looking east towards cabins. Proposed site for dam and reservoir is in background. (6/9/09)